CSAH HATU HATU 18-SALCI -85

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

William H. Culmer House 33 C Street Salt Lake City Salt Lake County HABS No. UT-85

- Louise T. Taft, Photographer July, 1985
- UT-85~1 EAST FRONT AND NORTH SIDE
- UT-85-2 WEST AND SOUTH SIDES
- UT-85-3 SOUTHEAST CORNER TOWER, DETAIL OF UPPER LEVELS, LOOKING SOUTHWEST
- UT-85-4 NORTH SIDE, DETAIL OF BAY WINDOW
- UT-85-5 EAST FRONT DOORWAY, DETAIL OF GLASS
- UT-85-6 INTERIOR, FIRST FLOOR, STAIRWAY TO SECOND FLOOR, LOOKING SOUTHWEST
- UT-85-7 INTERIOR, FIRST FLOOR, PARLOR, LOOKING SOUTHWEST TO LIVING ROOM
- UT-85-8 INTERIOR, FIRST FLOOR, LIVING ROOM, DETAIL OF FIREPLACE
- UT-85-9 INTERIOR, FIRST FLOOR, DINING ROOM, LOOKING NORTHWEST
- UT-85-10 INTERIOR, FIRST FLOOR, DINING ROOM, DETAIL OF SECCO PAINTING ON WEST WALL
- UT-85-11 INTERIOR, FIRST FLOOR, MAIN HALL LOOKING EAST
- UT-85-12 INTERIOR, SECOND FLOOR, STAIRWAY LOOKING WEST
- UT-85-13 INTERIOR, SECOND FLOOR, STAIRWAY LOOKING EAST
- UT-85-14 INTERIOR, SECOND FLOOR, TOWERS ROOM OFF OF SITTING ROOM, LOOKING SOUTHEAST
- UT-85-15 INTERIOR, THIRD FLOOR OF TOWER, DETAIL OF WINDOW, LOOKING SOUTHWEST